! (Bi)	** 99.5%	" 99.0%	99.5%
#\$%&'	0	O	0
* (Fe)	+0.002%	+0.002%	, 0.002%
- (Cu)	+0.01%	+0.02%	, 0.01%
. (Ag)	+0.03%	+0.05%	, 0.03%